

## **Drymix for Stained Glass Cement**

1 part Portland Cement  
2 parts Plaster of Paris  
4 parts powdered whittings\*

\* Chalk, calcium carbonate, or athletic field marking lime

### **Liquid Component**

(add when making batches)

50% Gum Turpentine  
50% Boiled Linseed Oil

Make cement to the consistency of peanut butter; apply with a scrub brush using circular motions to get into and under lead came flanges; remove excess; clean and dry and polish with a second scrub brush and several applications of powdered whiting.